


Case Studies - August 2020

Appeared in print as "Headworks and Biosolids Management"





City looks to oxygen for odor control

Washing system helps eliminate FOG problem

Problem: A large north Florida regional wastewater system was battling FOG up to 4 feet thick that was blanketing lift station walls and equipment. Dry-weather spills exacerbated the problem and drove a search for solutions.

Solution: The agency selected the EP-1300 well-washing and pretreatment system from Anue Water Technologies.

Result: The system eliminated the FOG in two hours. Spills were nonexistent, and confinedspace entry for cleaning was no longer necessary. Expenses for a boom truck and two operators for two hours on each occasion were eliminated, reducing maintenance costs by up to 20% annually. The agency now operates 15 EP-1300s and plans to add more. **800-559-7159**; <u>www.anuewater.com</u>